


NUCLEAR DIVISION ORGANIZATIONAL-FUNCTIONAL CHART



NUCLEAR DIVISION ORGANIZATIONAL-FUNCTIONAL CHART

Block One

1. Responsible to the Operations Squadron Commander for the proficiency of the Nuclear Division.
2. Supervise inspection and surveillance of source fissionable materials and the storage of same.
3. Responsible for all courier operations involving Nuclear material in DOD custody.
4. Supervise courier and salvage appraisal training.
5. Responsible for coordination with AEC to insure availability of components, and with Sandia Corporation to insure that that equipment is available for use during an operation.
6. Supervise maintenance, calibration, and inspection of test and handling equipment.
7. Responsible for compliance of the Nuclear Division with directives concerning administration, safety, security and economy.
8. Normally reports with "A" shift.

Block Two

1. Supervise the operation of the nuclear team, under the direct supervision of the Nuclear Officer in charge.
2. Insure proper maintenance, calibration, and inspection of test and handling equipment.
3. Insure availability of required equipment and transportation for courier operations.
4. Insure adherence to and familiarity with all pertinent publications.